

### List of Reference Characters

	A	amplitude
5	D	data input of Q
	f	frequency
	t	time
	PNCode	pseudo-noise code
	Q	shift register
10	Q1-Qn	stages of shift register
	Sender A	transmission signal generator
	Sender B	transmission signal generator
	Sender C	transmission signal generator
	TAKT	clocking rate for control of pulse repetition
15		frequency
	10	PN-code generator
	12	XOR-gate
	14	switch
20	16	switch




Fig. 1




Fig. 2




Fig. 3




Fig. 4




Fig. 5




Fig. 6




Fig. 7




Fig. 8




Fig. 9




Fig. 10